

VQ Models DHC-2 Beaver Manual Addendum

Please note an error in the manual for the .46 Size VQ Models DHC-2 Beaver.

On Page 5, Section 6 shows two collets supplied for attaching the tail wheel to the axle, this is incorrect only one collet is supplied/required as per the diagram below.

